

RECEIVED FROM

DATE REC'D. 3-8-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO. 322	DRAWING NUMBER	DWG. DATA FOR STANDARD PART NO. 72	DWG. REV. 0	LOT NO. 23	CLASS NUMBER	ORDER NUMBER	BUY OR CONS. NO.	ACCT. OF W.O. NO.	REMARKS
100	DRAWING NO. AND DESCRIPTION 730175-48 Pulver Screws					100				
<p>RECEIVED BY: <i>[Signature]</i> INSPECTED BY: <i>[Signature]</i> DATE: 3/9/57</p> <p>REJECTS RETURNED ON SHIP. MEND NO.</p>										

RECEIVING INSPECTION REPORT
 HYCON MFG. COMPANY
 2961 E. COLORADO ST., PASADENA, CALIF.

RECEIVED FROM

DATE REC'D. 3-11-57

P.O. NO.

VENDOR PACKING SLIP NO.

CHARGE TO QUANTITY RECEIVED	CONTRACT CODE NO. 322	DRAWING NUMBER	DWG. DATA FOR STANDARD PART NO. 36	DWG. REV. 0	LOT NO. 22	CLASS NUMBER	ORDER NUMBER	BUY OR CONS. NO.	ACCT. OF W.O. NO.	REMARKS
40	DRAWING NO. AND DESCRIPTION 732015 Sprayer					40				
<p>RECEIVED BY: <i>[Signature]</i> INSPECTED BY: <i>[Signature]</i> DATE: 3/11/57</p> <p>REJECTS RETURNED ON SHIP. MEND NO.</p>										

To supersede H.C. Insp. Report #11301